

Illustrated Parts List - IPL Update



Product Name(s)

T536LiXP

Description of change

IPL correction for Gen I and Gen II regarding keypad and crankcase.

Comments

For T536LiXP Gen.2 the customer needs to buy Wiring assy in order to get a Key pad.
For T536LiXP Gen.1 customers can buy key pad separately.

Introduced from

Serial number / Date	Remark

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Crankcase	6	581 05 38-02	Crankcase Assy	581 69 09-01	
Electric Control Unit Gen.2 from S/N 20180600615	3	582 71 34-02	Wiring assy	582 71 34-01	